IN RE: INVESTIGATION OF ACCIDENT ON THE DEFROIT, JACKSON & CHICAGO BAILWAY NEAR MICHIGAN CENTER, MICH., ON JULY 1, 1914.

On July 1, 1914, there was a head-end collision on the Detroit, Jackson & Chicago Reilway near Michigan Center, Mich., which resulted in the death of I passenger and the injury of 15 passengers, one of whom afterwards died, and I employee. After investigation of this accident the Chief Inspector of Safety Appliances reports as follows:

This part of the Detroit, Jackson & Chicago Railway is a single-track standard-gauge electric line. No block signal system is in use, trains being operated by train orders and time-card rights. Train dispatching is done by telephone. Machines containing train order blanks are located in the various telephone booths where train orders are received by trainmen. The conductor receives and writes the train order and the motorman repeats the order to the dispatcher, by whom it is then made complete. The motorman then resoves two copies of the order while a third copy passes into the lover part of the machine where it remains until removed.

Westbound train No. 157 consisted of motor ear No. 7790 and was in charge of Sonductor Southard and Motorman Blashfield, bound from Detroit, Mich., to Jackson, Mich. On arriving at Dunn, Mich., at 9:30 s.m., the erew in charge received train order No. 59 reading as follows:

Meet train No. 38 car 7771 at Glendale. Meet train No. 158 car 35 at Alma. Meet train No. 46 car unknown at Page.

Train No. 157 left Dunn at \$132 a.m., 10 minutes late and at 10:52 a.m., collided with eastbound train No. 46 at a point about 1 mile east of Page, while running at a speed estimated to have been about 25 miles per hour.

Eastbound train No. 46 consisted of motor ear No. 773 in charge of Conductor Rice and Motormen McCormick, bound from Jackson to Detroit. Train No. 46 left the station at Jackson at 10:35 a.m., on time, and on its arrival at the car born at 10:40 a.m. the onew received train order No. 58, reading as follows:

"Most train 197, car 7700 at Center."

Venter, the time-card name for Michigan Center, is 2.19 miles east of Page, the meeting point provided for trains No. 46 and 157 in the order which was sent to the crew of train No. 157, and the lessence of train order No. 58, making Center the meeting point, therefore resulted in a lap order. Train No. 46 passed Page and collided with train No. 157 between Page and Center as above stated. The speed of the train at the time of collision had been reduced to about 6 or 8 miles per hour.

1、微能水管

and the state of t Both cars were derailed by the shock of the collision and the forward end of each was telepooped and badly damaged.

En - 1 ' State 1 15 ' to the 2 the less come 1 - 15 to 100.

The collision occured in the middle of a curve of 8 degrees about 700 feet in length. West of the curve the track is straight for about 800 feet, while east of the ourve it is straight for about 4,000 feet. The grade is slightly descending was westbound trains. On the incide of the curve there is a row of trees extending from a point 2,100 feet each of the point of collision to within 100 feet of the same. The range of vision of the motorman of the eastbound our was limited to about 750 feet, while the range of vision of the motormen of the westbound our was limited to about 200 feet. The weather was cloudy and a light rain had been falling.

Train Dispatcher Cottroll, who isound the train orders involved in this accident, stated that in issuing train order No. 39 to the crew of train No. 157, he intended to name Conter as the me ting point, but in some way which he could not explain he erroneously hamed Page as the meeting point. When he made the entry on his train sheet about five minutes afterwards he showed trains Nos. 48 and 157 as meeting at Center, which was the point he originally had in mind. When the grew of train No. 46 asked for orders at the par barn at Jack on, more than one hour efterwards, he looked at his train cheet, saw that it showed Center as the meeting point of that train with train No. 157 and without looking at his copy of train order No. 39 issued train order No. 58, naming Center as the meeting point instead of Page.

The cause of this accident was the issuence of a inp order, for which Dispatcher Cottzell was responsible.

Dispatcher Cottrell was employed as a conductor in A pril. 1909, and was made an extra dispatcher in February, 1912, and regular dispatcher in Spetember of the mane year. He was considered to be a reliable and efficient employee. At the time of the accident he had been on duty about 4 hours, after a period off duty of about 16 bours.

On April 15, 1912, the Commission investigated a head-end collision on this reilroad near Dexter, Mich., a point located on the same division as Center and about 24 miles distant therefrom. It cooursed under nearly the same circumstances as provided in this case, a lap order being the cause. The Commission has also investigated a rear-end collision near Debroit on October 15, 1911, and a head-end collision mear Waterville, Mich., on June 6, 1913.

In the reports covering the secidents occurring on this eystem which have been investigated, attention has been called to inadequate and unsafe rules, bad operating conditions and the faults of the dispetching system in use, and in those reports the adoption of some adequate form of block-signal system has been recommended. Ead this recommendation been adopted, and an adoquate block-signal system been installed, this addident undoubtedly would not have cocurred, notwithstanding the mistake of the dispatcher at fault.